

# NRO DECLASSIFICATION/RELEASE INSTRUCTIONS ON FILE

23 January 1963

MEMORANDUM FOR: The Special Group

SUBJECT: Permission for a TACKLE Mission  
[REDACTED]

25X1D

25X1D

1. Two TACKLE missions directed at [REDACTED]

25X1D

25X1D

[REDACTED] have failed because of camera mal-

function. Permission is requested to mount another mission at this target as soon as feasible.



2. The Hy Con camera experts through extensive tests have determined that the cause of malfunction lies in the vacuum solenoid. This device which controls the movement of the film has been rebuilt to replace a cadmium lining with nickel. This replacement, thoroughly tested, will be installed before any further TACKLE missions are made. This should be accomplished by 23 January. The answer to why this fault has not shown itself in previous years is obscure but it is believed associated with the age and protracted use of the equipment.

25X1A

[REDACTED]  
HERBERT SCOVILLE, JR.  
Deputy Director  
(Research)

NRO

25X1A

Copy 1--Office of the Special Assistant to the President  
for National Security Affairs  
2--The Under Secretary of State for Political Affairs  
3--Under Secretary of Defense  
4--DCI  
5--DDCI  
6--  
7--DDR  
8--DDR  
9--DDI (via   
10--D/NRO (S)  
11--AD/OSA  
12--Intel/OSA  
13--Special Group Officer/DDR  
14--RB/OSA/DDR

25X1A

25X1A

NRO

25X1A